



Press release - 20/02/2012



## NEWTON HARNESS: REQUEST FOR INSPECTION



### Request for inspection of the NEWTON harness sternal attachment point

During a periodic inspection on a NEWTON harness, improperly positioned safety stitching was found on one of the loops of the sternal attachment point.

**As a precautionary measure, Petzl is asking all of its customers to inspect the safety stitching on the loops of the sternal attachment point on all NEWTON harnesses.**

The products affected by this request for inspection are the NEWTON C73\*\*\* type harnesses with serial numbers equal to or less than 11365\*\*\*.

This inspection is simple. It involves measuring the safety stitching on the loops of the sternal attachment point.

For the inspection of your NEWTON type harness, download the procedure at [www.petzl.com.au/newtonalert.html](http://www.petzl.com.au/newtonalert.html)

We are well aware of the inconvenience that this request may cause and thank you in advance for your help.

Learn more at: [www.petzl.com/newton](http://www.petzl.com/newton)

---

#### PETZL

Z.I. Crolles  
Cidex 105A  
38 920 Crolles  
France  
33 (0)4 76 92 09 00  
[www.petzl.com](http://www.petzl.com)

#### Press relations contact:

Christina Chipman  
+61 2 9966 9800  
[christina@spelean.com.au](mailto:christina@spelean.com.au)

#### Petzl contact:

Paul Lidgard  
+61 2 9966 9800  
[newtonalert@petzl.com.au](mailto:newtonalert@petzl.com.au)