



Press release - 20/02/2012



NEWTON HARNESS: REQUEST FOR INSPECTION



Request for inspection of the NEWTON harness sternal attachment point

During a periodic inspection on a NEWTON harness, improperly positioned safety stitching was found on one of the loops of the sternal attachment point.

As a precautionary measure, Petzl is asking all of its customers to inspect the safety stitching on the loops of the sternal attachment point on all NEWTON harnesses.

The products affected by this request for inspection are the NEWTON C73*** type harnesses with serial numbers equal to or less than 11365***.

This inspection is simple. It involves measuring the safety stitching on the loops of the sternal attachment point.

For the inspection of your NEWTON type harness, download the procedure at www.petzl.com.au/newtonalert.html

We are well aware of the inconvenience that this request may cause and thank you in advance for your help.

Learn more at: www.petzl.com/newton

PETZL

Z.I. Crolles
Cidex 105A
38 920 Crolles
France
33 (0)4 76 92 09 00
www.petzl.com

Press relations contact:

Christina Chipman
+61 2 9966 9800
christina@spelean.com.au

Petzl contact:

Paul Lidgard
+61 2 9966 9800
newtonalert@petzl.com.au