



PRODUCT INFORMATION:

Non-compliance of adjustable webbing on PODIUM seat reference S071AA00



ISSUE:

We noticed a non-compliance during the manufacturing of the first new models of PODIUM seats. Products concerned by this non-compliance were manufactured between March 2018 and the end of September 2018. On some of these seats, the attachment part of the adjustable webbing is not large enough to allow the connection of a karabiner.



We estimate this default to be 15% of the total PODIUM seats manufactured.

CORRECTIVE ACTION:

To be able to connect any karabiner in the adjustable webbing, it is necessary to replace this spare part.



Spare adjustable webbing for PODIUM seat

To obtain a spare set of webbing at no charge, please request them on the Petzl Australia website:

<https://www.petzl.com.au/2018/11/21/podium-straps-replacement/>

We apologise for any inconvenience caused and will ensure a prompt replacement is sent once you lodge your request on the Petzl Australia website.

Thank You.